

HSA BUILDING FACT SHEET

Building No. / Name Building #2502 - 2507
Installation Fort Monmouth

Original / Former Use

Food Commissary warehouses; general warehouses; vacant buildings

Current Tenant / Use

(CERDEC) Fabrication and Integration

Construction Information

2507 appears newer than other buildings, likely due to renovations.

| | |
|---|---|
| Date of Construction: <u>1942</u> | Construction Material: <u>Concrete</u> |
| Total Sq. Footage: <u>42,752 (all)</u> | Renovation Information: <u>Unknown</u> |
| Floors: <u>1 (all)</u> | Current Building Status: <u>Existing</u> |

Sources of Information (*Document No's Used, Interviews, etc.*)

- Document Reviews – None
- Site Visit and Interviews – Ref. 005

Radiological Data Summary (*RCOPCs, Impacted Room(s) / Area(s), etc.*)

Radiological monitors are sometimes part of equipment installed into the Humvees and other vehicles, but they do not have radiological sources. No indications of radiological materials or contamination were observed.

Preliminary MARSSIM Classifications

Non-Impacted

Site Visit Information (*Date Toured, Site Contact, Security Issues, Photos Taken*)

Site visit conducted June 11, 2006 by Bob Dover, accompanied by representatives from Shaw Environmental. Site contacts were Otto Kirse (Shop Foreman, 2502), Kyle Reber (Machinist Manager, 2503), Tom Dillie (Chief, 2506), and Pat Gervolin and Charlie Johnson (Mechanical Engineering Technicians, 2507). Site visit included interview with building operators, visual inspection, and photographs.

Additional Information

2502: Integration facility to incorporate electronics and other equipment into vehicles (usually Humvees) before sending out to field sites to test. Only waste here is aluminum. No tests involve radioactive sources and no materials would have radioactive commodities.

2503: Fabrication and machine shop; no evidence of radioactive materials.

2504: Offices, shipping and receiving.

2506: Paint and sign shop, installation facility (materials fabricated in 2502 are installed into the Humvees in this building). Two HazMat storage sheds are outside this building, along with a used oil tank.

2507: Bays to park Humvees and other vehicles for outfitting; final stop before vehicles are sent out for testing.

**HSA and Addendum to Environmental Condition of Property
Fort Monmouth**

Representative Photographs/Floor Plans/Drawings

Floor plans provided.



Fort Monmouth, Building 2502 (North)



Fort Monmouth, Building 2503 (West)



Fort Monmouth, Building 2504 (East)



Fort Monmouth, Building 2506 (West)

**HSA and Addendum to Environmental Condition of Property
Fort Monmouth**



Fort Monmouth, Building 2507 (West)