

HSA BUILDING FACT SHEET

Building No. / Name Building #2539 (CECOM)
Installation Fort Monmouth

Original / Former Use

N/A

Current Tenant / Use

CECOM Safety administrative offices

Construction Information

Date of Construction:	<u>1942</u>	Construction Material:	<u>Concrete & cinderblock</u>
Total Sq. Footage:	<u>7,836</u>	Renovation Information:	<u>Early 1990s</u>
Floors:	<u>1</u>	Current Building Status:	<u>Existing</u>

Sources of Information (*Document No's Used, Interviews, etc.*)

- Document Reviews – None
- Site Visit and Interviews – Ref. 001

Radiological Data Summary (*RCOPCs, Impacted Room(s) / Area(s), etc.*)

Building contains only administrative offices, with no radiological material use or storage. Records kept at this office show that no radiological incidents or spills have occurred on the Main Post or Charles Wood Areas. Additionally, no buildings have been decommissioned in these areas.

Preliminary MARSSIM Classifications

Non-Impacted

Site Visit Information (*Date Toured, Site Contact, Security Issues, Photos Taken*)

Site visit conducted July 10, 2006 by Bob Dover, Michele Driscoll, and Hank Siegrist, accompanied by representatives from Shaw Environmental. Site contact is Barry Silber, CECOM RSO. Site visit included interviews with Mr. Silber and Laboratory Supervisor, Jason Simpson.

Additional Information

The field team received a CD-ROM from Mr. Silber with CECOM files, surveys, and reports. This office is POC for multiple Army-wide NRC licenses for radioactive commodities, but they are not stored at this location.

Representative Photographs/Floor Plans/Drawings

Floor plan provided.