

**HSA BUILDING FACT SHEET**

**Building No. / Name** Building #602  
**Installation** Fort Monmouth

---

**Original / Former Use**

N/A

**Current Tenant / Use**

(I2WD) Secure research and fabrication area

**Construction Information**

<b>Date of Construction:</b> 1997	<b>Construction Material:</b> Concrete foundation with aluminum walls
<b>Total Sq. Footage:</b> <u>6,000</u>	<b>Renovation Information:</b> <u>N/A</u>
<b>Floors:</b> <u>1</u>	<b>Current Building Status:</b> <u>Existing</u>

**Sources of Information** (*Document No's Used, Interviews, etc.*)

- Document Reviews – Ref. 045, Ref. 047, Ref. 101
- Site Visit and Interviews – Ref. 001, Ref. 021

**Radiological Data Summary** (*RCOPCs, Impacted Room(s) / Area(s), etc.*)

- Building 602 was noted as a building of interest on a list provided by Barry Silber of the CECOM Safety Office (Ref. 045).
- CECOM Safety inventory lists (Ref. 047) mention the use of instruments containing a Ni-63 source.

Detecting equipment (ACADA) containing Ni-63 sealed source was integrated into field military vehicles. According to the managers and operators, these instruments are no longer kept at or used at this facility. According to leak test data for GL devices provided by Mr. Goldberg, GL devices previously existing inside the building have been moved to other buildings and affected areas used for radioactive commodities indicate no contamination above the lower limits of detection.

**Preliminary MARSSIM Classifications**

Non-Impacted

**Site Visit Information** (*Date Toured, Site Contact, Security Issues, Photos Taken*)

Site visit conducted June 13, 2006, by Michele Driscoll, accompanied by representatives from Shaw Environmental. Site contact is Bill Kimble. Site visit included interview with building operators and visual inspection (photographs were not permitted).

**Additional Information**

Building 601 is currently an office and warehouse and is moving to the newly constructed Building 603 to allow space for new Research Labs.

**Representative Photographs/Floor Plans/Drawings**

Floor plan provided. Tenant requested that no photos be taken of this building.